Page 1 of 2



Illinois Environmental Protection Agency

Bureau of Water • 1021 N. Grand Avenue E. • P.O. Box 19276 • Springfield • Illinois • 62794-9276

Division of Water Pollution Control

Construction Site Storm Water Discharge Incidence of Non-Compliance (ION)

Permittee Information: Name: Lake County Division of Transportation Street Address: 600 W Winchester Road City: Libertvville State: IL Zip Code: 60048 County: Lake Phone: 847-377-7400 Email: gpetko@lakecountyil.gov Construction Site Information: Site Name: Delany Road Reconstruction Street Address: Susnset Ave to York House Rd City: Wadsworth/Waukegan State: IL Zip Code: 60085 Latitude: 42 24 34.68 Longitude: 87 54 13.44 25, 26 (Deg) (Min) (Sec) Section Cause of Non-Compliance Suspended sediment exiting from a flared end section into adjacent detention pond. The sedim from 2 drainage structures across the street which had excavated material placed on top/inside measures. Actions Taken to Prevent Any Further Non-Compliance Lake County Permitting has notified the contractor responsible for the incident. The contractor restoring the disturbed areas as well as cleaning out any sediment that has entered the storms within 24 hours. Environmental Impact Resulting From the Non-Compliance	46N Township ent was likely of the inlet pro	. ILR10
Name: Lake County Division of Transportation Street Address: 600 W Winchester Road City: Libertyville State: IL Zip Code: 60048 County: Lake Phone: 847-377-7400 Email: gpetko@lakecountyil.gov Construction Site Information: Site Name: Delany Road Reconstruction Street Address: Susnset Ave to York House Rd City: Wadsworth/Waukegan State: IL Zip Code: 60085 Latitude: 42 24 34.68 Longitude: 87 54 13.44 25, 26 (Deg) (Min) (Sec) (Deg) (Min) (Sec) Section Cause of Non-Compliance Suspended sediment exiting from a flared end section into adjacent detention pond. The sedim from 2 drainage structures across the street which had excavated material placed on top/inside measures. Actions Taken to Prevent Any Further Non-Compliance Lake County Permitting has notified the contractor responsible for the incident. The contractor restoring the disturbed areas as well as cleaning out any sediment that has entered the storm swithin 24 hours.	P.O. Box:	11E Range coming otection
Street Address: 600 W Winchester Road City: Libertvville State: IL Zip Code: 60048 County: Lake Phone: 847-377-7400 Email: gpetko@lakecountyil.gov Construction Site Information: Site Name: Delany Road Reconstruction Street Address: Susnset Ave to York House Rd City: Wadsworth/Waukegan State: IL Zip Code: 60085 Latitude: 42 24 34.68 Longitude: 87 54 13.44 25, 26 (Deg) (Min) (Sec) (Deg) (Min) (Sec) Section Cause of Non-Compliance Suspended sediment exiting from a flared end section into adjacent detention pond. The sedim from 2 drainage structures across the street which had excavated material placed on top/inside measures. Actions Taken to Prevent Any Further Non-Compliance Lake County Permitting has notified the contractor responsible for the incident. The contractor restoring the disturbed areas as well as cleaning out any sediment that has entered the storm s within 24 hours.	P.O. Box:	11E Range coming otection
City: Libertyville State: IL Zip Code: 60048 County: Lake Phone: 847-377-7400 Email: gpetko@lakecountyil.gov Construction Site Information: Site Name: Delany Road Reconstruction Street Address: Susnset Ave to York House Rd City: Wadsworth/Waukegan State: IL Zip Code: 60085 Latitude: 42 24 34.68 Longitude: 87 54 13.44 25, 26 (Deg) (Min) (Sec) (Deg) (Min) (Sec) Section Cause of Non-Compliance Suspended sediment exiting from a flared end section into adjacent detention pond. The sedim from 2 drainage structures across the street which had excavated material placed on top/inside measures. Actions Taken to Prevent Any Further Non-Compliance Lake County Permitting has notified the contractor responsible for the incident. The contractor restoring the disturbed areas as well as cleaning out any sediment that has entered the storm s within 24 hours.	46N Township ent was likely of the inlet pro	11E Range coming otection
Phone: 847-377-7400	46N Township ent was likely of the inlet pro	Range coming otection
Construction Site Information: Site Name: Delany Road Reconstruction Street Address: Susnset Ave to York House Rd City: Wadsworth/Waukegan State: IL Zip Code: 60085 Latitude: 42 24 34.68 Longitude: 87 54 13.44 25, 26 (Deg) (Min) (Sec) (Deg) (Min) (Sec) Section Cause of Non-Compliance Suspended sediment exiting from a flared end section into adjacent detention pond. The sedim from 2 drainage structures across the street which had excavated material placed on top/inside measures. Actions Taken to Prevent Any Further Non-Compliance Lake County Permitting has notified the contractor responsible for the incident. The contractor restoring the disturbed areas as well as cleaning out any sediment that has entered the storm s within 24 hours.	Township ent was likely of the inlet pro	Range coming otection
Site Name: Delany Road Reconstruction Street Address: Susnset Ave to York House Rd City: Wadsworth/Waukegan State: IL Zip Code: 60085 Latitude: 42 24 34.68 Longitude: 87 54 13.44 25, 26 (Deg) (Min) (Sec) (Deg) (Min) (Sec) Section Cause of Non-Compliance Suspended sediment exiting from a flared end section into adjacent detention pond. The sedim from 2 drainage structures across the street which had excavated material placed on top/inside measures Actions Taken to Prevent Any Further Non-Compliance Lake County Permitting has notified the contractor responsible for the incident. The contractor restoring the disturbed areas as well as cleaning out any sediment that has entered the storms within 24 hours.	Township ent was likely of the inlet pro	Range coming otection
Street Address: Susnset Ave to York House Rd City: Wadsworth/Waukegan State: IL Zip Code: 60085 Latitude: 42 24 34.68 Longitude: 87 54 13.44 25, 26 (Deg) (Min) (Sec) (Deg) (Min) (Sec) Section Cause of Non-Compliance Suspended sediment exiting from a flared end section into adjacent detention pond. The sedim from 2 drainage structures across the street which had excavated material placed on top/inside measures. Actions Taken to Prevent Any Further Non-Compliance Lake County Permitting has notified the contractor responsible for the incident. The contractor restoring the disturbed areas as well as cleaning out any sediment that has entered the storm s within 24 hours.	Township ent was likely of the inlet pro	Range coming otection
City: Wadsworth/Waukegan State: IL Zip Code: 60085 Latitude: 42 24 34.68 Longitude: 87 54 13.44 25, 26 (Deg) (Min) (Sec) (Deg) (Min) (Sec) Section Cause of Non-Compliance Suspended sediment exiting from a flared end section into adjacent detention pond. The sedim from 2 drainage structures across the street which had excavated material placed on top/inside measures. Actions Taken to Prevent Any Further Non-Compliance Lake County Permitting has notified the contractor responsible for the incident. The contractor restoring the disturbed areas as well as cleaning out any sediment that has entered the storm s within 24 hours.	Township ent was likely of the inlet pro	Range coming otection
Latitude: 42 24 34.68 Longitude: 87 54 13.44 25, 26 (Deg) (Min) (Sec) (Deg) (Min) (Sec) Section Cause of Non-Compliance Suspended sediment exiting from a flared end section into adjacent detention pond. The sedim from 2 drainage structures across the street which had excavated material placed on top/inside measures. Actions Taken to Prevent Any Further Non-Compliance Lake County Permitting has notified the contractor responsible for the incident. The contractor restoring the disturbed areas as well as cleaning out any sediment that has entered the storm s within 24 hours.	Township ent was likely of the inlet pro	Range coming otection
(Deg) (Min) (Sec) (Deg) (Min) (Sec) Section Cause of Non-Compliance Suspended sediment exiting from a flared end section into adjacent detention pond. The sedim from 2 drainage structures across the street which had excavated material placed on top/inside measures. Actions Taken to Prevent Any Further Non-Compliance Lake County Permitting has notified the contractor responsible for the incident. The contractor restoring the disturbed areas as well as cleaning out any sediment that has entered the storm s within 24 hours.	Township ent was likely of the inlet pro	Range coming otection
Cause of Non-Compliance Suspended sediment exiting from a flared end section into adjacent detention pond. The sedim from 2 drainage structures across the street which had excavated material placed on top/inside measures. Actions Taken to Prevent Any Further Non-Compliance Lake County Permitting has notified the contractor responsible for the incident. The contractor restoring the disturbed areas as well as cleaning out any sediment that has entered the storm s within 24 hours.	ent was likely of the inlet pro	coming otection
Suspended sediment exiting from a flared end section into adjacent detention pond. The sedim from 2 drainage structures across the street which had excavated material placed on top/inside measures. Actions Taken to Prevent Any Further Non-Compliance Lake County Permitting has notified the contractor responsible for the incident. The contractor restoring the disturbed areas as well as cleaning out any sediment that has entered the storm s within 24 hours.	of the inlet pro	otection_
from 2 drainage structures across the street which had excavated material placed on top/inside measures. Actions Taken to Prevent Any Further Non-Compliance Lake County Permitting has notified the contractor responsible for the incident. The contractor restoring the disturbed areas as well as cleaning out any sediment that has entered the storm s within 24 hours.	of the inlet pro	otection_
Actions Taken to Prevent Any Further Non-Compliance Lake County Permitting has notified the contractor responsible for the incident. The contractor restoring the disturbed areas as well as cleaning out any sediment that has entered the storm s within 24 hours.		
Actions Taken to Prevent Any Further Non-Compliance Lake County Permitting has notified the contractor responsible for the incident. The contractor restoring the disturbed areas as well as cleaning out any sediment that has entered the storm s within 24 hours.	stated that the	
Lake County Permitting has notified the contractor responsible for the incident. The contractor restoring the disturbed areas as well as cleaning out any sediment that has entered the storm s within 24 hours.	stated that the	
Environmental Impact Resulting From the Non-Compliance	ewer system s	
Because all but a small area of the pond is frozen, only a plume of suspended sediment from the observed. No other environmental impacts are evident.	e flared end w	as
Actions Taken to Reduce the Environmental Impact Resulting From the Non-Compliance The contractor will take corrective action tomorrow including inlet protection repairs and cleanin areas will be closely monitored in the future to ensure no other environmental impacts are occu		
Any person who knowingly makes a false, fictitious, or fraudulent material statement, orally or in commits a Class 4 felony. A second or subsequent offense after conviction is a Class 3 felony. (3/19/19 Owner Signature: Date:	415 ILCS 5/44(F	
Paula Trigg, P.E. County Engineer		
Printed Name: Title:	ν.	

IL 532 2105 WPC 624 Rev. 10/2011

This Agency is authorized to require this information under Section 4 and Title X of the Environmental Protection Act (415 ILCS 5/4, 5/39). Failure to disclose this information may result in: a civil penalty of not to exceed \$50,000 for the violation and an additional civil penalty of not to exceed \$10,000 for each day during which the violation continues (415 ILCS 5/42) and may also prevent this form from being processed and could result in your application being denied. This form has been approved by the Forms Management Center.